Inspection Report



Client: Sample Client Inspector: Nicholas Lemmon (482309)

Address: 7282 55TH AVE E #112 Arrival Date: <Insert Date>
Bradenton, FL 34203 Arrival Time: <Insert Time>

Exterior Conditions

Water Main: ✓ OFF on arrival - OFF on departure Gutters/Soffits: ✓ Appears normal from ground

Driveway: ✓ Good Condition Lanai: ✓ Clean but wet from rain

Lawn: Pool: ✓ Appears to be clear & clean

Thermostat / Humidistat Settings

HVAC - Primary HVAC - Secondary

 Set:
 75 T
 Set:
 75 T

 Actual:
 74 T
 Actual:
 74 T

 Humidity:
 55.00%
 Humidity:
 55.00%

Handheld Meter Reading: Handheld Meter Reading:

Temperature:75 FTemperature:75 FHumidity:55.14%Humidity:55.44%

Interior Conditions

Kitchen

Additional Rooms / Areas

Den/Office:	✓ Good Condition✓ Good Condition	Launary Room:	► Evidence of pests (See Notes)
	B	edrooms en la company de l	
Master Bedroom: Master Closet:	✓ Good Condition✓ Good Condition	Middle Bedroom: Third Bedroom:	✓ Good Condition✓ Good Condition
	В	athrooms	
	Master Bathroom		Full Bath
Sink: Toilet: Tub: Shower: General Condition:	 ✓ Ran water, no apparent leaks ✓ Flushed, no apparent leaks ✓ Ran water, no apparent leaks ✓ Ran water, no apparent leaks ✓ Good Condition 	Sink: Toilet: Tub: Shower: General Condition:	 ✓ Ran water, no apparent leaks ✓ Flushed, no apparent leaks ► Faucet is leaking (See Notes) ✓ Ran water, no apparent leaks ✓ Good Condition
	Half Bathroom		
Sink: Toilet: General Condition:	✓ Ran water, no apparent leaks✓ Flushed, no apparent leaks✓ Good Condition		
		Garage	
General Condition: Sink: Interior Door:	✓ Good Condition✓ Ran water, no apparent leaks✓ Locked and secure	Exterior Door: Overhead Door:	✓ Locked and secure✓ Ran up/down working properly
	Autos	s & Golf Carts	
Vehicles:	✓ Started & idled during inspection		
		Notes	
_			